

# **RUSTOP**

#### **DESCRIZIONE**

## IDEALE PER SUPERFICI DELICATE

Acido per la rimozione delle puntinature. Detergente acido per la totale rimozione dei residui ferrosi, carboniosi e da smog derivanti dal trasporto ferroviario. Elimina puntinature e residui di cere polimeriche e paraffiniche da vetri e carrozzeria. Da utilizzare manualmente o negli impianti automatici per la deceratura delle vetture nuove. Nelle corrette modalità di utilizzo non intacca la carrozzeria, le plastiche ed i profili in alluminio.

- Non macchia la vernice
- Delicato su alluminio e plastica
- Bassa schiuma

#### **CARATTERISTICHE CHIMICO-FISICHE**

PARAMETRI	VALORI
Aspetto fisico	Liquido limpido incolore
Odore	Caratteristico
pH	1,0 ± 0,5
pH 1%	2,3 ± 0,5

## **RUSTOP**

#### **DESCRIPTION**

## IDEAL FOR DELICATE SURFACE

Acid-based iron pitting remover. Acid-based detergent designed to completely remove ferrous or carbonaceous residue or smog build-up caused by railway transportation. Gets rid of the pitting effect, removes polymeric and paraffin wax residue from glass and bodywork. For use manually or in automatic systems for the dewaxing of new Used in the correct way described below, does not damage the body, plastics and aluminum profiles.

- Does not harm the car paint
- Delicate on aluminium and plastic
- Low foam

#### PHYSICAL-CHEMICAL PARAMETERS

PARAMETERS	VALUES
Physical aspect	Limpid liquid, uncoloured
Odour	Peculiar
pH	1,0 ± 0,5
pH 1%	$2.3 \pm 0.5$



## **APPLICAZIONE E DOSAGGIO**

Impiego manuale: Diluire come da tabella. Spruzzare la soluzione con nebulizzatore o pompa proporzionale sulla superficie asciutta, attendere qualche minuto e procedere con la fase di lavaggio.

Impianti automatici: Far aspirare, con pompa dosatrice o sistema Venturi, nell'apposito arco di nebulizzazione dell'impianto automatico adottando i dosaggi indicati nella tabella.

Difficoltà di	MANUALE/AUTOMATICO	
rimozione	Rustop: Acqua	%
Alta	1:3	25
Media	1:5	17
Bassa	1:9	10

CONTIENE TENSIOATTIVI CONFORMI AL REG. 648/2004/CE

#### **APPLICATION**

Manual use: Dilute as in the table. Spray the solution with a nebulizer or proportional pump onto the dry surface. Wait for some minutes and proceed with the washing step.

Automatic systems: Suck, with dosing pump or Venturi system, into the arc spraying of the automatic plant using dosages indicated in the table.

Removal	MANUAL/AUTOMATIC	
difficulty	Rustop: Water	%
Heavy	1:3	25
Medium	1:5	17
Light	1:9	10

CONTAINS SURFACTANTS ACCORDING TO REG. 648/2004/CE